










Soil Vapor: SE Hennepin Ave – Minneapolis

Building Mitigation Status



-  General Mills/Henkel Corp. Superfund Site historic disposal area
-  Approximate groundwater TCE plume
-  No mitigation required.
-  Mitigation system required - not yet installed.
-  Vapor mitigation system has been installed.
-  Mitigation will be offered but is not required based on sampling results.
-  Sampling access denied.
-  Soil gas monitoring area
Long-term soil gas monitoring will be conducted in the public right-of-way.

All properties within the mitigation area will be offered a vapor mitigation system.

*Sampling status current as of March 31, 2015.

Service Layer Credits: ©2013 Esri, DeLorme, NAVTEQ